



ENVIRONMENTAL CLAIM VALIDATION SUMMARY

UNIMICRON TECHNOLOGY CORP

Unimicron Technology Corporation Shanying I Plant

Report Number:

323543-4160

Validation Period:

05 Feb 2024 - 05 Feb 2025

Claim:

Unimicron Technology Corporation Shanying I Plant has achieved Zero Waste to Landfill Gold Operations, 99% diversion, with 7% Thermal Processing with Energy Recovery.

Method:

Environmental Claim Validation Procedure (ECVP) for Zero Waste Classifications, UL 2799A First Edition, Dated July 20, 2018

Facility:

No. 177, 179, Shanying Rd. Shanding Vil., Guishan Dist., Taoyuan, 333, Taiwan